Procedure Title:	End of Observation
Last Date Modified:	28/05/98 14:10:24
Author:	Kate Adamson

Purpose of Procedure:

OM End of Observation procedure executes the move of the Filter wheel to Blocked and configures the OM DPU to IDLE

Initial State: OM ON in SCIENCE

Final State: OM ON in IDLE

Step	Time	Activity/Remarks	Command	TM Verification
		ED- GO TO IDLE		
2		Set Filter Wheel to Blocked		
2 .1	00:00:00	Set Filter Wheel Number. Filter Wheel to be set to Blocked - Filter number 0, Filter position 1200. (Filter Wheel parameter not in Database!)	**HS6000** **H7604** SET FW NUMBER	
2 .2	00:00:02	Move Filter Wheel to Blocked Await Filter Wheel move Event Report. (TBC) Packet ID	**HS6000** **H5600** MOVE FW	H2300= Blocked H5265=1200
2 .3	00:02:00	Wait for Filter Wheel to Move. Inform DPU which Filter is in use. (TBC if TC to be sent)	**HS6000** **H7241** LOAD FILT CONF	
3		Goto Idle Mode		
3 .1	00:00:02	Go to IDLE Mode (TBC TM confirmation of OM Mode status)	**HS1020** **H9002** GOTO IDLE	H5405=Operating Mode H5450=DPUOS
4		END OF PROCEDURE		